

BECKER DRILLS LIMITED

194 TORYORK DRIVE WESTON 486, ONTARIO, CANADA

> TELEPHONE: (416) 749-5241

12th November, 1969.

Mr. David Tobias, 30, Forden Avenue, Westmont, Quebec.

Dear Mr. Tobias:

You requested further information on the results of our drilling at Oak Island, and as discussed during our conversation Becker normally only keep records on hole numbers, depths, time, etc but not on the sample recovered. This is because our clients usually take the samples from our cyclone recovery system and examine the material themselves as the results are confidential and this was the procedure followed at Oak Island.

We have provided you with our drill reports which you have, however, while we keep any information on results that we know of confidential this does not mean we are unaware of some of the details.

To my knowledge there were four holes that had particularily significant results. In these holes from Don Thompson, Driller and Horst Pasche, Supervisor, I recall that bedrock was encountered at around 155 feet and was drilled further by triconing and/or blasting to 190 some feet where a cavity was encountered. Then our double walled drive pipe was pounded down to the 190 feet depth and on down through the cavaties as far as 200 feet or more.

In four holes at least, a cavity was encountered and wood and in one hole a piece of china was brought up to the surface recovery unit. Also wood was brought up by our triconing drilling operation.

I hope this is the information you require.

Yours truly,

J. F. Short.